

Service Technical News

Title: Motor Service Part Number Errata in Parts' Manuals

Models: MLZ-KP09/12/18NA2-U1 & NTXUKS 09/12/18 A112BA

Manuals: OBB802B / OBBT802A, pages #7

1. Summary.

(1) Parts' Manuals OBB802B for Indoor MLZ-KP##NA2-U1 Legacy Models and OBBT802A for Indoor NTXUKS##A112BA Trane Models, both in their pages #7, indicate the usage of the Motor with Service Part number U01A01300 to be used for the following models:

- MLZ-KP09NA2-U1,
- MLZ-KP12NA2-U1,
- MLZ-KP18NA2-U1,
- NTXUKS09A112BA,
- NTXUKS12A112BA &
- NTXUKS18A112BA.

(2) Motor U01A01300 does not fit into the models listed above due to their rubber assembly attached and their different shaft, see Figure 1 below.



Figure 1

2. Changes.

(1) Please use/request the Motor U01A03300 (see Figure 2 below), for the models listed above, instead of the U01A01300.



Figure 2

(2) Change Manuals OBB802B & OBBT802A to reflect the correction. TBD.